

## Product Change Notice:

1001-011-01101: Molding/tooling modifications:

## For USB connector 1001-011-01101 - with date codes AFTER 20/01:


Tooling for 1001-01101 (CONNECTOR USB, 1.1, 4P, A/M, ULTRA FLAT,  $1\mu''$ , SMT, R/A, HORIZONTAL) had to be adjusted, which created slight changes on the PCB layout.


## Adjusted/new PCB

 layout:
 Old PCB Layout:

 .X = +/- 0.20mm
 .X = +/- 0.38mm

 .XX = +/- 0.15mm
 .XX = +/- 0.25mm





Regards,

H. Meyer CnC Tech