

PDN Number:	20160204001	PDN Date:	2/09/2016
Title:	Discontinuance of LP3984xxx devices		
Customer Contact:	PCN Manager	Dept:	Quality Services
Last date to order:	2/09/2017	Last date to ship:	08/09/2017
Change Type:	Product Discontinuance - End Of Life		

Product Discontinuance Notification Details

Description of Discontinuance:

Texas Instruments, Incorporated (TI) is announcing the discontinuance of the LP3984xxx devices. A non-cancelable, non-refundable life time buy is being offered per the date show above. Recommended replacements are being offered as shown in the Product Affected Section.

NOTE: There are no samples offered for withdrawn/obsolete products. For assistance on selection of any replacement products or samples, please contact your local sales representative.

Reason for Discontinuance:

The LP3984 requires poly fuse etch which is no longer manufacturable.

Product Affected:

DEVICES BEING DISCONTINUED	RECOMMENDED REPLACEMENT PRODUCT	REPLACEMENT CODES
LP3984IMF-1.5	LP3990 Product	Replacement codes may vary per selected part.
LP3984IMF-1.5/NOPB		
LP3984IMF-1.8		
LP3984IMF-1.8/NOPB		
LP3984IMF-3.1/NOPB		
LP3984IMFX-1.8/NOPB		
LP3984ITP-2.9/NOPB		
LP3984ITPX-1.8/NOPB		

Replacement Codes:

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com