



Eaton  
5735 W. Las Positas Blvd #100  
Pleasanton, CA 94588  
www.eaton.com/electronics

## Product Change Notice

PCN#: EE-PCN17002

1/9/2017

### CLASSIFICATION OF CHANGE:

End of Life (EOL)

### DESCRIPTION OF CHANGE:

TDC17 family which is 5mm RoHS compliance fast acting ferrule fuse.

### REASON FOR CHANGE:

Product has reached end of life.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Not Applicable

### PARTS FAMILIES AFFECTED:

TDC17-1-R	BK1-TDC17-1-R
TDC17-2-R	BK1-TDC17-2-R
TDC17-3-R	BK1-TDC17-3-R
TDC17-5-R	BK1-TDC17-5-R

### TIME SCHEDULE:

Last Time Buy Date: April 14, 2017

Last Time Shipment Date: May 15, 2017

Existing inventory is saleable and should not be returned

### ISSUED BY:

Product Manager: Wayne Wang

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).