

Tel:818-701-4933

Process Change Notification

Aug-18th-2015

Title: MCC Moves DO-221AC(SMAFL) production line to Yangzhou Plant

PCN#: 081815-1

Planned Effective Date Code :1538

Reliability Data:N/A

Samples contact: Sales@mccsemi.com

For question concerning this notification: techsupport@mccsemi.com

Notification Type: Final Process/Product Change Notification(FPCN)

MCC will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <u>techsupport@mccsemi.com</u>

www.mccsemi.com



20736 Marilla Street, Chatsworth, CA91311 Tel:818-701-4933

Description and purpose :

MCC will move DO-221AC(SMAFL) package to yangzhou plant due to our surface mount packages plant re-location strategy, this movement will not cause function and reliability issues.

For any concern about this PCN, pls feel free to contact your local sales representative or us directly via above E-mail address.

Affected Parts List:

SK310AFL-TP	SK56AFL-TP	US1JFL-TP
SK32AFL-TP	SK58AFL-TP	US1KFL-TP
SK33AFL-TP	SS110FL-TP	US1MFL-TP
SK34AFL-TP	SS12FL-TP	US2AFL-TP
SK35AFL-TP	SS13FL-TP	US2BFL-TP
SK36AFL-TP	SS14FL-TP	US2CFL-TP
SK38AFL-TP	SS15FL-TP	US2DFL-TP
SK510AFL-TP	SS16FL-TP	US2GFL-TP
SK5150AFL-TP	SS18FL-TP	US2JFL-TP
SK5200AFL-TP	US1AFL-TP	US2KFL-TP
SK52AFL-TP	US1BFL-TP	US2MFL-TP
SK53AFL-TP	US1CFL-TP	
SK54AFL-TP	US1DFL-TP	
SK55AFL-TP	US1GFL-TP	
	SK32AFL-TP SK33AFL-TP SK34AFL-TP SK35AFL-TP SK36AFL-TP SK510AFL-TP SK5150AFL-TP SK5200AFL-TP SK52AFL-TP SK52AFL-TP SK53AFL-TP	SK32AFL-TP SK58AFL-TP SK33AFL-TP SS110FL-TP SK34AFL-TP SS12FL-TP SK35AFL-TP SS13FL-TP SK36AFL-TP SS13FL-TP SK36AFL-TP SS14FL-TP SK36AFL-TP SS14FL-TP SK36AFL-TP SS14FL-TP SK510AFL-TP SS16FL-TP SK5150AFL-TP SS18FL-TP SK5200AFL-TP US1AFL-TP SK52AFL-TP US1BFL-TP SK53AFL-TP US1CFL-TP SK53AFL-TP US1DFL-TP

www.mccsemi.com